


Conveyance between process at the time of part assembly

Before

Dangerous overhead

Bad trackability

Slow vertical movement




After

Overhead free

Cover wide moveable range

Quick moving



Work weight	50kg (Parts)
Frequency	5 times/day

Arm	Extension arm + $\phi 100$ + Scara + arm
Attachment	hook

Point

Safety

Work Efficiency

Wide Operation Area