

MC

Set work to Machining Center




Before

Backache from awkward position

Difficult to access

Injury by dropping work




After

Side approach

Safe installation

Safe work lifting



Work weight	30kg (Cylindrical work)
Frequency	60 times/day

Arm	Extension arm + $\phi 100$	
Attachment	Hook	

Point

Side access

Prevent backache

