


MC


Assembling assistant to machine tool



Before



After



Work weight	30kg (Parts)
Frequency	5 times/day

Arm	Extension arm + $\phi 125$	
Attachment	Clamp with reversing function	

Point

Work Efficiency

Improve operation

Reduce manpower

